



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

Sept 05, 2007

Supervisor DRZ

**Mine Name:** Cream Time Quarry  
**Operator Name:** Lanny Jensen (deceased)

**Permit number:** M/039/009  
**Inspection Date:** August 29, 2007  
**Time:** 11:30 pm

**Inspector(s):** Lynn Kunzler, DOGM

**Other Participants:** none

**Mine Status:** inactive (undergoing reclamation)

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation
10. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in the area.

#### Inspection Summary:

There has been little reclamation activity at this site over the last year. About a year ago, a neighboring operator spent a few hours performing reclamation. Reclamation at the site is now about 50% completed. Overburden pile along the western boundary (northern half of the site) still need to be regraded. There is also some small pits and highwall areas that need to be regraded between the overburden piles and the eastern boundary.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

Continue to monitor this site when in the area.

**Inspector's Signature**

*[Handwritten Signature]*

LK:pb

O:\M039-Sanpete\S0390009-Creamtime\inspections\Insp-08272007.doc